

DRONEINSPECTOR **USA**

INSPECTION REPORT

SAMPLE DRONE INSPECTION
RESIDENTIAL ROOF

09/15/2026



Inspection Report



Property Information

Job Name
Private

Job Type
Residential

Phone Number
N/A

Email Address
N/A

About This Report

Report Created
09/15/2026

Assets
18

Added Photos
10

Annotations
3

Images With Confirmed Damage
5

General Information

Completed by
Brian Nagorski

Completed on
09/11/2026

Inspect List Type
N/A



PO001

Photo Added by Brian Nagorski on
09/14/2026 10:29 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 10:29 AM CDT
Front of homeowners home.




PO002

Photo Added by Brian Nagorski on
09/14/2026 10:29 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 10:29 AM CDT
Front overview of roof





PO003

Photo Added by Brian Nagorski on
09/14/2026 10:48 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 10:48 AM CDT
Front right elevation overhead of the roof.



PO004

Photo Added by Brian Nagorski on
09/14/2026 10:58 AM CDT

Additional Notes

No additional notes have been added.





PO010

Photo Added by Brian Nagorski on
09/14/2026 11:00 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 11:00 AM CDT
Hail hits
Soft metal damage
rusted valleys
wind damage on some lifting shingles



PO008

Photo Added by Brian Nagorski on
09/14/2026 11:12 AM CDT

Additional Notes

No additional notes have been added.





PO011

Photo Added by Brian Nagorski on
09/14/2026 11:13 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 11:13 AM CDT
Noticeable hail hits with drone footage



PO017

Photo Added by Brian Nagorski on
09/14/2026 11:14 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 11:14 AM CDT
Storm damage displays across this roof
picture






PO022

Photo Added by Brian Nagorski on
09/14/2026 11:23 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 11:23 AM CDT
Normal wear and tear



PO012-T

Photo Added by Brian Nagorski on
09/15/2026 10:55 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 10:55 AM CDT
Thermal image of the roof, detects darker, colder areas not necessarily moisture but something to keep an eye on.
The darker the color palette the colder areas, lighter means warm/hot.





PO006-1 GENERAL OBSERVATION

Annotated by Brian Nagorski on
09/14/2026 10:14 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 10:14 AM CDT
-Rusted valleys is a common way for water to intrude causing mold/mildew, ice and water problems down the road if not addressed.




PO001-1 GENERAL OBSERVATION

Annotated by Brian Nagorski on
09/14/2026 10:15 AM CDT

Additional Notes

Brian Nagorski
09/14/2026 10:15 AM CDT
Front view of homeowner's home.

Brian Nagorski
09/14/2026 10:17 AM CDT
Above the bottom right window, some siding damage






PO013-T-1 GENERAL OBSERVATION

Annotated by Brian Nagorski on
09/15/2026 10:56 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 10:56 AM CDT
Cold temperature means air coming through.



PO003

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Creased Shingle	2
Soft Metal Damage	2

NOTE



CONFIRMED DAMAGE


Soft Metal Damage4

PO004

CLOSE UP EXAMPLES



NOTE




CONFIRMED DAMAGE

Creased Shingle1
Rust1

PO006

CLOSE UP EXAMPLES



NOTE



CONFIRMED DAMAGE

Hail Hit	8
Rust	3
Soft Metal Damage	1

PO008

CLOSE UP EXAMPLES



NOTE



CONFIRMED DAMAGE

Creased Shingle	1
Hail Hit	16
Soft Metal Damage	1

PO010

CLOSE UP EXAMPLES



NOTE

Flight Information



Photo Locations from Scan

GENERAL INFO

Pilot in Command
Brian Nagorski

Drone ID Number
1581F5FJC245500D3V2H

Scan Date
09/11/2026

Start Time
9:53 AM CDT

End Time
9:59 AM CDT

Total Flight Time
00:06:16

ALTITUDES

 **Safe Height**
80 ft