


STANDARD OPERATING PROCEDURE

EDGE BANDER



**ONLY TRAINED PERSONNEL
AUTHORISED TO OPERATE THIS MACHINE**

Identified Hazards

- Heat / Burns
- Eye Injuries
- Exposure to moving & rotating parts
- Waste Materials
- Nip Points
- Electricity

Personal Protective Equipment Requirements to Operate



Other | Additional PPE Requirements:

Restrain long / loose hair, remove / contain loose jewellery, no loose clothing

Operating Instructions

Pre-Operational Safety Checks

- Inspect the machine for any obvious damage, including lead, plug end and guarding and that the machine has a current electrical safety tag.
- Ensure suitable & safe work area provided with adequate lighting and ventilation, free from congestion & tripping hazards.
- Locate and be familiar with the operation of the ON/OFF switch and emergency stop button where fitted.
- Remove from the immediate work area, any flammable or volatile substances / materials.
- Electrically isolate the machine from the power supply if unsafe, making repairs or adjustments, or servicing.

Operational Safety Checks

- **NEVER** operate a faulty piece of equipment. Report any faults, problems or hazards **IMMEDIATELY**.
- Ensure required PPE is available and worn.
- Where available, select the correct heat setting for the task to be undertaken.
- Do not put your hand or any part of your body directly in front of the nozzle of the heat gun.
- Always maintain a balanced stance when operating the machine.
- Do not leave the machine unattended when operational.
- Clean up and dispose of any debris from the work area both during and upon completion of the task.

REFER TO THE MANUFACTURER'S OPERATIONAL MANUAL FOR FULL SAFETY REQUIREMENTS