




INSPECTION REPORT



Inspection Report



Job Address: Private (Minnesota)



FS001-T

Photo Added by Brian Nagorski on
09/15/2026 11:01 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:01 AM CDT
Thermal Aerial overview of the hotel.
- Lots of cold spots, something to keep an eye on.



LM003

Photo Added by Brian Nagorski on
09/15/2026 11:02 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:02 AM CDT
Left aerial elevation of hotel.

Job Address: Private (Minnesota)




LM085

Photo Added by Brian Nagorski on
09/15/2026 11:07 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:07 AM CDT
Another overview photo of the hotel.




LM020-T

Photo Added by Brian Nagorski on
09/15/2026 11:22 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:22 AM CDT
This is also showing trapped moisture, could
be from insulation or beneath the shingles




LM061-T

Photo Added by Brian Nagorski on
09/15/2026 11:36 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:36 AM CDT
[More thermal photos](#)




LM081-T

Photo Added by Brian Nagorski on
09/15/2026 11:38 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:38 AM CDT
Moisture/water intrusion detection on the
rear elevation.






PO007

Photo Added by Brian Nagorski on
09/15/2026 11:45 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:45 AM CDT
Cracked/missing shingle






LM061-T-1 MOISTURE SURVEY

Annotated by Brian Nagorski on
09/15/2026 11:35 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:35 AM CDT
Don't worry this is just a shadow.



LM090-T-1 MOISTURE SURVEY


Annotated by Brian Nagorski on
09/15/2026 11:39 AM CDT

Additional Notes

Brian Nagorski
09/15/2026 11:39 AM CDT
More moisture intrusion on the rear
elevation.



Flight Information



tions from Scan

ALTITUDES



Full Subject Photo
233 ft



Lawn Mower
89 ft



Detailed Checks (while traveling)
61 ft



Safe Height
65 ft

Scan Date
09/15/2026

Start Time
9:55 AM CDT

End Time
10:08 AM CDT

Total Flight Time
00:13:16